

2052 Platinum Road Apopka, Florida 32703 Phone: 407.464.0539 Fax: 407.464.0779



## **STOP Check Your System**

The failure that resulted in the replacement of this compressor, most likely was a result of some systems problem.

### **CHECK CAREFULLY FOR THE CAUSE**

Look for excessive discharge pressures or temperatures, low suction pressure, slugging, flooding, proper operation of contactors, proper operation of oil safety controls, and leaks in refrigerant or oil.

**Failure to find and correct such a system problem will result in a second failure.**