




Don't Trap Oil in Your Suction Line Filter Dryer!!!



THE PROBLEM:

The installation of a suction line filter drier as shown above left, can create an **oil trap** that can **absorb liquid** refrigerant during the off cycle and cause **slugging** problems **during system operation.**

THE SOLUTION:

When installing a suction line filter drier follow the two examples shown about **right!!!**