

2052 Platinum Road • Apopka, Florida 32703 • Phone: 407.464.0539 • Fax: 407.464.0779



CHECK EVAPORATOR AND CONDENSOR

Make sure they are clean and free of air restriction. Poor air flow can shorten compressor life, and lower unit efficiency. Check evaporator pulley to make sure there is no excessive wear. If a deep groove is present this will lower unit performance. Make sure belts are not worn out and that they are tight.